

Release GC-Prevue v31.1 Notes

Table of Contents

NEW AND IMPROVED FEATURES 2

 ADDED PLUGIN FUNCTIONS..... 2

ITEMS FIXED SINCE V30.2..... 3

New and Improved Features

Added Plugin functions

A number of plugin functions have been added to enhance the customization of the product. Details can be found within the Intellisense for the plugin.

Items Fixed since v30.2

This list is customer reported issues fixed for this release.

- #754 Updated the handling of G32 and G33 commands to correctly compensate the rout path.
- #753 Fixed a minor inconvenience that displayed when tabbing between fields in the Move and Jump dialogs and not auto-selecting the current value.
- #749 64bit version of the software crashed when using Write with PDF to create outputs using the old Plotter Definition Files.
- #747 Older GWKs load at 2x size in the 64version of the software. Problem fixed.
- #742 Some older dialog boxes caused a crash of the application in Windows 11 if right click was implemented in certain areas. Problem is related to context sensitive help.
- #736 Fixed a zoom issue at the extremes of the new available area. The software was not fully taking into account the extents.
- #734 Microsoft Visual C++ component update caused a crash during Import of Gerber files in 64bit version – hotfix issued to resolve.
- #733 The Layer Switch function caused a crash when closing an empty GWK. Resolved.
- #730 Update of internal components resulted in the Initially Maximize Graphical View option no longer applying. Resolved.
- #729 Import of a Drill file into an existing GWK resulted in selected data across multiple hidden layers. The import no longer incorrectly affects existing data.